

(On I-80, Exit 267 South) 2096 Moscow Road, Moscow, Iowa 52760

Phone: (800)321-3494 or (563)724-3396 Fax: (563)724-3408 Internet: www.hwhcorp.com

PRODUCT/SERVICE BULLETIN

ISSUE DATE: March 8, 1993

TO: All O.E.M Manufacturers and Installers

FROM: HWH CORPORATION

RE: Repairing or Installing an AP8525 Leveling Jack

REPAIRING OR INSTALLING AN AP8525 LEVELING JACK

Anytime an AP8525 jack (16,000# for a 610 System) is installed or repaired, the following procedure must be followed:

- 1. Turn the system on and bring the jacks to the vertical position.
- 2. Extend and retract the jacks in the manual mode three to four times before lifting the coach.

NOTE: Items 1 and 2 must be followed to purge air from the jacks and the hydraulic lines. If this procedure is not followed, damage may result to the actuator.